

SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC4521) was tested in accordance with the Road Safety (General) Regulations 2009 on the 14/03/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC5275) was tested in accordance with the Road Safety (General) Regulations 2009 on the 14/03/2017.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC5204) was tested in accordance with the Road Safety (General) Regulations 2009 on the 18/03/2016.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.

Date:



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748