

SCHEDULE 2

Regulation 6(3)

CERTIFICATE UNDER SECTION 78A

I am a licensed surveyor within the meaning of the **Surveying Act 2004** and I am approved by the Roads Corporation for the purposes of section 78A of the **Road Safety Act 1986**.



I certify that the shortest distance, expressed in metres, that would be travelled by a motor vehicle travelling on the southbound carriageway of the Hume Freeway between:

- (a) the vehicle detectors at 109 metres South of Broadford-Flowerdale Road Broadford and
- (b) the vehicle detectors at Station Street, Wallan East

is 24,750 metres.

Signature of person issuing certificate:



Name:  – Licensed Surveyor Registration No. 

Date: ^{fw} 20 November 2009



SCHEDULE 1A

Regulation 106(3)

CERTIFICATE UNDER SECTION 78A

I am a licensed surveyor within the meaning of the **Surveying Act 2004** and I am approved for the purposes of section 78A of the **Road Safety Act 1986** by the Roads Corporation.

I certify that the shortest distance, expressed in metres, that would be travelled by a motor vehicle travelling on the southbound carriageway of the Hume Freeway between:



(a) the vehicle detectors at 109 metres South of Broadford-Flowerdale Road, Broadford and

(b) the vehicle detectors at Station Street, Wallan East

is 24,750 metres.

Signature of person issuing certificate:



Name:  – Licensed Surveyor Registration No. 

Date: 20 December 2006



CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC0943) was tested in accordance with the Road Safety (General) Regulations 2009 on the 03/10/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC1078) was tested in accordance with the Road Safety (General) Regulations 2009 on the 03/10/2017.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC1793) was tested in accordance with the Road Safety (General) Regulations 2009 on the 29/09/2016.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748