

**SCHEDULE 3**



**Regulation 52**

**CERTIFICATE UNDER SECTION 83**

**ROAD SAFETY ACT 1986**

The road safety camera Gatsometer GTC-GS11 (No. 1706) was tested in accordance with the Road Safety (General) Regulations 2009 on the 05/03/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

**SCHEDULE 3**



**Regulation 52**

**CERTIFICATE UNDER SECTION 83**

**ROAD SAFETY ACT 1986**

The road safety camera Gatsometer GTC-GS11 (No. 1719) was tested in accordance with the Road Safety (General) Regulations 2009 on the 05/03/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748



## SCHEDULE 3

Regulation 52

**CERTIFICATE UNDER SECTION 83****ROAD SAFETY ACT 1986**

The road safety camera Gatsometer GTC-GS11 (No. 1706) was tested in accordance with the Road Safety (General) Regulations 2009 on the 06/03/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.






Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

**CERTIFICATE UNDER SECTION 83**  
**ROAD SAFETY ACT 1986**

The road safety camera Gatsometer GTC-GS11 (No. 1719) was tested in accordance with the Road Safety (General) Regulations 2009 on the 06/03/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

## SCHEDULE 3

Regulation 52

**CERTIFICATE UNDER SECTION 83****ROAD SAFETY ACT 1986**

The road safety camera Gatsometer GTC-GS11 (No. 1706) was tested in accordance with the Road Safety (General) Regulations 2009 on the 02/03/2017.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748


## SCHEDULE 3

Regulation 52

**CERTIFICATE UNDER SECTION 83****ROAD SAFETY ACT 1986**

The road safety camera Gatsometer GTC-GS11 (No. 1719) was tested in accordance with the Road Safety (General) Regulations 2009 on the 02/03/2017.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748